

SX-20 Cobalt Tank

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Walter / 575-454-3329

SX-20

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Teleso Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 1140 2/6/24

Facility: Gen House

Facility tag: 60-07

Pump and Storage

PMLU Status: Remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			Cobalt Storage + Tank to south in good condition
Drainage Around Facility	X			
Access to Facility	X			
Building Parking			X	
Fencing or Security			X	
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process	X			
Electrical				
Power supply	X			↓
Power distribution	X			
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-20
Cobalt Tank

PREPARED FOR:  FREEPORT-McMoRAN

SX-21

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2-24-21 14:30

Facility: Storage Facility tag: 1X-21 PMLU Status: Remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			N/A
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				N/A
Water Supply if present	X			N/A
Waste water if present	X			N/A
Other utilities if present				N/A
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			N/A
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-21
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-21
External View

PREPARED FOR:



SX-22

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2-5-24 14:15

Facility: Learning office PMLU Status: Remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			N/A
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure	X			
Mechanical				
HVAC if present	X			N/A
Water Supply if present	X			
Waste water if present	X			
Other utilities if present	X			
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present	X			
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-22
External View

PREPARED FOR: F&M FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-22
External View

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT:
200450-001

TASK
03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

SX-22
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-22
External View

PREPARED FOR:

FM
FREEPORT-
McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-22
Internal View

PREPARED FOR:

FREEPORT-McMoRAN

SX-24

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

IM + WN

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 1106 26/24

Facility: Leach Control Facility tag: 5X-24

Break room PMLU Status: remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				N/A
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security			3	X
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				X
Water Supply if present	X			
Waste water if present				X
Other utilities if present				X
Fire protection if present				X
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present	X			
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-24
External View

PREPARED FOR: F&M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-24
External View


PREPARED FOR: F&M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-24
External View

PREPARED FOR: F-M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-24
External View

PREPARED FOR:



FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-24
Internal View

PREPARED FOR: F&M FREEPORT- McMORAN

SX-25

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time:

Facility: *T. 6*

Facility tag: *5X-25*

Storage

PMLU Status: *Remaining*

Category	Condition			Comments
	Good	Fair	Poor	
Civil				<i>N/A</i>
Condition of Site	↓			
Drainage Around Facility				
Access to Facility	↓			
Building Parking				
Fencing or Security				
Foundation				
Foundation	↓			
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	↓			
Framing: Roofs				
Framing: Internal	↓			
If Concrete structure				
Mechanical				
HVAC if present			⚡	↓
Water Supply if present			⚡	
Waste water if present			⚡	
Other utilities if present			⚡	
Fire protection if present			⚡	
Piping				
if facility is not building				↓
if facility is process				↓
Electrical				
Power supply				↓
Power distribution				
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-25
External View

PREPARED FOR: F&M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-25
External View

PREPARED FOR:  FREEPORT- McMoRAN
--



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-25
External View

PREPARED FOR: F&M FREEPORT-McMORAN




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-25
External View

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-25
External & Internal View

PREPARED FOR: F&M FREEPORT- McMORAN

SX-26

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT-McMoRAN
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/24 11:25

Facility: (701SX)

Facility tag: SX-26

PMLU Status: repairs

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs NA				
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present ? N/A				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-26
External View

PREPARED FOR:  FREEPORT-McMoRAN

SX-27

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2-5-24 14:20

Facility: SX Office Building

Facility tag: SX-27

PMLU Status: Remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			N/A
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			N/A
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present	X			
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT:
200450-001

TASK
03

PREPARED BY:

TELESTO
SOLUTIONS INCORPORATED

SX-27
External View

PREPARED FOR:

F-M
FREEPORT-
McMORAN

SX-Conex

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 09/14/2024 14:30

Facility: CONEX Storage

Facility tag: SX-CONEX

PMLU Status: Remaining



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				nu ↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX-Conex
External View

PREPARED FOR: F&M FREEPORT- McMoRAN

SX-Chemical Area

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 2/16/24 13:00

Facility: SX

Facility tag: MF-SX

PMLU Status: Remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security	X			
Foundation				
Foundation				
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				

PMLU 1303



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX
Chemical Area

PREPARED FOR:

FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX
Chemical Area

PREPARED FOR: F-M FREEPORT- McMORAN





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

SX
Chemical Area

PREPARED FOR: F&M FREEPORT-McMoRAN

Attachment C
CP Area Field Forms and Photographs

CP-01

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

Date/Time: 02/05/2021

1:45 pm

Facility: Guard House Facility tag: SA-01

Change room PMLU Status: remains


Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility		X		rusty gutters, water ponding
Access to Facility	X			
Building Parking				nn
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		Dented walls, hole in wall
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				nn
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-01
External View


PREPARED FOR: F-M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-01
External Damage

PREPARED FOR:  FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-01
External Damage

PREPARED FOR: F-M FREEPORT- McMORAN

CP-02

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 6/2/05/2024 3:15 PM

Facility: Concentrator Facility tag: CP-62

PMLU Status: Remaining





Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility		X		
Access to Facility	X			
Building Parking		X		
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X	X		cracked floor slabs
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				nn
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				nn
Piping				
if facility is not building				
if facility is process	X			
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-02
External & Internal View

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-02
External Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-03

Place path and filename here

PROJECT:	TASK
PREPARED BY:	
	

--

PREPARED FOR:

Date/Time: 02/27/2024 2:45

Facility: Shop & warehouse

Facility tag: CP-03

PMLU Status: Remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				na
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			

CP-05

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

Date/Time: 03/12/2024

13:30 AM

Facility: ELECTRIC

Facility tag: CP-05

ROOM

PMLU Status: REMAINS

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			Pooling along eastern edge
Drainage Around Facility		X		
Access to Facility	X			
Building Parking		X		
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				↑ ↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-05
Molly Tank - External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-05
External View & Damage

PREPARED FOR:



FREEPORT-McMoRAN





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-05
External Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-06

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

IM + WJN

Pump House

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2/5/24 1456

Facility: Elect Room

Facility tag: CP-2506

PMLU Status: DEMO



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site				
Drainage Around Facility			X	
Access to Facility		X		steep
Building Parking				N/A
Fencing or Security				N/A
Foundation				
Foundation		X		
Floor Slabs	X			outside pipe stand foundations OK
If process Facility: Cond of equip fnds	X			cut side upper decking rusty
Structure				
Framing: Walls			X	
Framing: Roofs		X		-Bldg skel is poor @ base
Framing: Internal			X	-mmmm holes
If Concrete structure				-North side wall pillar rusted mid bldg - north, several others have web missing @ bottom
Mechanical				
HVAC if present	N/A			
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process	X			
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				N/A
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-06
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
External Damage

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
External Damage

PREPARED FOR:






PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-06
Internal View

PREPARED FOR:






PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
Internal Damage

PREPARED FOR: F&M FREEPORT- McMORAN




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
Internal Damage

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
Internal Damage

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-06
External Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-08

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 2/16/24 0945

Facility: Old Asarco Facility tag: CP-08

Storage Sheds

PMLU Status: remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				N/A
Condition of Site	X			See map notes & photos 4 Bldgs historical SW Bldg (gen shab Dn old maps)
Drainage Around Facility	X			
Access to Facility	X			
Building Parking			X	
Fencing or Security			X	
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls	X			sheds have damage
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				↓
if facility is process				
Electrical				
Power supply				↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors			X	
windows			X	
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External View & Damage

PREPARED FOR:  FREEPORT-McMoRAN




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External View

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External Damage

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-08 Internal View

PREPARED FOR:






PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External View & Damage

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
Internal View

PREPARED FOR: F-M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External View & Damage

PREPARED FOR: F&M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
External View

PREPARED FOR:






PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
Internal View & Damage – Shed 4

PREPARED FOR:

FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-08
Internal View

PREPARED FOR:



CP-09

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 2/5/24 14:25

Facility: Process W, T Facility tag: CPO9

PMLU Status: Keep




Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site				All Good, recently constructed
Drainage Around Facility				
Access to Facility				
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			- Minor surface spalling
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				- Great
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process	X			
Electrical				
Power supply	X			
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				N/A ↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-09
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-09
External View

PREPARED FOR: F&M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-09
External View & Damage

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-09
External View & Damage

PREPARED FOR: F&M FREEPORT- McMORAN

CP-10

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 02/05/2024


Facility: Fresh Water

Facility tag: CPIO

Tank

PMLU Status: Keep

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	✓			
Drainage Around Facility		✓		
Access to Facility	✓			
Building Parking N/A				
Fencing or Security				
Foundation				
Foundation	✓			
Floor Slabs				
If process Facility: Cond of equip fnds	✓			
Structure				
Framing: Walls		✓		Historic leak present IM
Framing: Roofs N/A				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present N/A				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				This is a tank
if facility is process	✓			
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-10
External View

PREPARED FOR:



CP-11

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 8/5/24 15:14

Facility: Thickeners

Facility tag: CP-11



Scraper North

PMLU Status: keep

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			North side pooling badly N/A
Drainage Around Facility		X		
Access to Facility	X			
Building Parking				
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			Minor surface rust @ base N/A ↓
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				N/A ↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building if facility is process	X			
Electrical				
Power supply	X			N/A ↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				N/A ↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-11
External View

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-11
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-11
External View

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-11
External Damage

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-11
External Damage

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-11 Equal Tank
External View**

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-11 Equal Tank
External Damage**

PREPARED FOR:



CP-12

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/05/2024

2:37

Facility: Laboratory Facility tag: CP-12

PMLU Status: remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			Improper Drainage inside
Drainage Around Facility		X		
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs		X		
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			Eye wash stations
Water Supply if present	X			
Waste water if present	X			
Other utilities if present	X			
Fire protection if present	X			
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			Fume hood vacuum fair + overs
Power distribution	X			
Lighting	X			
Other utilities if present	X			
Architectural				
Condition of Flooring	X			water Damage
Wall systems	X			
roofing		X		
ceilings	X	X		
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-12
Internal Damage

PREPARED FOR:



FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-12
Internal Damage

PREPARED FOR:



FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-12
Internal Damage

PREPARED FOR: F&M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-12
External Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-13

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/05/2024 2:15 PM

Facility: Ev/moly

Facility tag: 013



thickener

PMLU Status: remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site				Completely zoned off -> Heavy construction occurring
Drainage Around Facility				
Access to Facility				
Building Parking				
Fencing or Security				
Foundation				
Foundation				
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				

under maintenance



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-13
External View

PREPARED FOR: F&M FREEPORT- McMoRAN

CP-14

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 02/05/2024 2:23

Facility: CV Mairbner Facility tag: CP-121



PMLU Status: remaining

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			NM NM
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-14
External View

PREPARED FOR:  FREEPORT-McMoRAN

CP-15 & CP-16

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061




Date/Time: 2/12/14 14:07

Facility: Process Plant Facility tag: CP 15 + 16

Head tank PMLU Status: Keep

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	✓			N/A
Drainage Around Facility	✓			
Access to Facility	✓			
Building Parking				
Fencing or Security	✓			
Foundation				
Foundation	✓			
Floor Slabs	✓			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				N/A ↓ Steel tanks mmos surface rust outside
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				↓
if facility is process				
Electrical				
Power supply	X			N/A ↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				N/A ↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-15 & CP-16
External View**

PREPARED FOR:  FREEPORT- McMoRAN
--




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-15 & CP-16
External Damage**

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-15 & CP-16
External View**

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-15 & CP-16
External Damage**

PREPARED FOR:



**FREEPORT-
McMoRAN**



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

**CP-15 & CP-16
External Damage**

PREPARED FOR:



**FREEPORT-
McMORAN**

CP-17

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024

Facility: Tank

Facility tag: CP-17

PMLU Status: Repairs

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation				
Floor Slabs				rn nn
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-17
External View

PREPARED FOR: F&M FREEPORT- McMORAN

CP-18

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 2:18 2/9/24

Facility: Proc. Head Tank Facility tag: CP-18

PMLU Status: ??

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		Note historical leaks [O]
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				N/A ↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			Surface rust
if facility is process	X			
Electrical				
Power supply				N/A ↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				N/A ↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-18
External View

PREPARED FOR:






PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-18
External Damage

PREPARED FOR:

FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-18
External Damage

PREPARED FOR:



FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-18
External Damage

PREPARED FOR:  FREEPORT- McMoRAN
--

CP-19

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

WN

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2/6/24 0930

Facility: Env. Bldg Facility tag: CP-19
PMLU Status: Keep



Category	Condition			Comments
	Good	Fail	Poor	
Civil				N/A
Condition of Site	X			Warehouse - historical Bldg
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security	X			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		Tim outside sheeting
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present	X			one loan heater
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				↓
if facility is process				
Electrical				
Power supply				↓
Power distribution				
Lighting				
Other utilities if present				
Architctural				
Condition of Flooring	X			
Wall systems		X		
roofing	X			
ceilings	X			
doors		X		
windows			X	
points of egress		X		



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-19
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-19
External Damage

PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001 TASK 03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-19
Internal View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-19
Internal View

PREPARED FOR:

FREEPORT-McMORAN

CP-21

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/06/2024 09:42 am

Facility: *Personnel mx* Facility tag: *CD 21*

air storage

PMLU Status: *remains*



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		<i>Dents and holes</i>
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-21
External View & Damage

PREPARED FOR: F&M FREEPORT-McMORAN

CP-22

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024


9:45

Facility: Lime Unloading

Facility tag: CP-22

PMLU Status: repair

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT:	TASK
200450-001	03
PREPARED BY:	
TELESTO SOLUTIONS INCORPORATED	

CP-22
External View & Damage

PREPARED FOR:


CP-23

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024

9:40

Facility: Lime

Facility tag: CP-23

Storage

PMLU Status: Remaining

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-23
External View & Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-24

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/06/2024 9:25 AM

Facility: Concentrate Storage Facility tag: CP-24

PMLU Status: Remarks



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			cracks present
Floor Slabs		X		
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-24
External View & Damage

PREPARED FOR: F&M FREEPORT- McMORAN

CP-25

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine


Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024 9:30

Facility: Concentrate Pump House Facility tag: CA-25 PMLU Status: Remaining

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			missing gutter
Drainage Around Facility		X		
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems				
roofing				
ceilings				
doors	X			
windows				
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-25
External View & Damage

PREPARED FOR:



FREEPORT-McMORAN

CP-27

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

Date/Time: 02/06/2024

9:45

Facility: Collector

Facility tag: C-27

Tanks

PMLU Status: Remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			nn
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			Holes inside of tank
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-27
External View & Damage

PREPARED FOR: F&M FREEPORT- McMORAN

CP-28

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024

Facility: Shop
Storage

Facility tag: CP-2B

PMLU Status: remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			Roofing between buildings
Drainage Around Facility		X		
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation		X		Cracks in foundations and flooring
Floor Slabs		X		
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				n
Water Supply if present	X			
Waste water if present	X			n
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-28
External View

PREPARED FOR: F&M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-28
External Damage

PREPARED FOR:  FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-28
Internal Damage

PREPARED FOR:  FREEPORT-McMORAN

CP-31

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 02/15/24 1457

Facility: Iron Hoop Substation

Facility tag: CP-31

PMLU Status: Keep

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			No entry photo inspect from outside
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security	X			
Foundation				
Foundation	X			- plenty of clearance between bolts and concrete edge N/A
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				N/A
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply	X			N/A
Power distribution	X			
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				




PROJECT: 200450-001	TASK 03
------------------------	------------

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-31
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-31
External View

PREPARED FOR:

F&M
FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-31
External View & Damage



PREPARED FOR: F&M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-31
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT:	TASK
200450-001	03
PREPARED BY:	
TELESTO SOLUTIONS INCORPORATED	

CP-31
External View & Damage

PREPARED FOR:


CP-32

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/05/2024

1:55 pm

Facility: wet crush

Facility tag: CP-32

Recycle Plant PMLU Status: remain




Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			large Drainage issue up front na
Drainage Around Facility		X		
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation				cannot see foundation
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		minor cracks, hole in wall, rusted siding
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				na
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				doors rusted
Wall systems				
roofing	X			
ceilings	X			
doors		X		
windows				
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-32
External View


PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-32
External Damage

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-32
External Damage

PREPARED FOR:  FREEPORT- McMORAN
--



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-32
External Damage

PREPARED FOR:

FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-32
Internal View

PREPARED FOR:  FREEPORT-McMoRAN

CP-33

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/05/2021

2:00 PM

Facility: Dry recycle Facility tag: CP-33
Crush Plant PMLU Status: Panned MS



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			water pooling below machines m m
Drainage Around Facility		X		
Access to Facility		X		
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs				
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				

Requires Respirator



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-33
External damage

PREPARED FOR: F&M FREEPORT- McMORAN

CP-34

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024

10:00 am

Facility: Pipe

Facility tag: CP-344

Storage Shed

PMLU Status: remaining

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X	V		loose site Annual
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-34
External View

PREPARED FOR:  FREEPORT-McMoRAN

CP-35

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 03/14/2024

Facility: Portable

Facility tag: CP-35

Storage Shed

PMLU Status:

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			n/a
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				n/a
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors	X			
windows				
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-35
External View & Damage

PREPARED FOR:  FREEPORT-McMoRAN

CP-36

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

wm

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 2/12/24 0915

Facility: SEWER Plant

Facility tag: CP-36

PMLU Status: Demo

Category	Condition			Comments
	Good	Fair	Poor	
Civil				N/A
Condition of Site		X		"Free" tanks - slips trips + falls
Drainage Around Facility			X	
Access to Facility	X	X		
Building Parking			X	
Fencing or Security			X	
Foundation				
Foundation				X X
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		Surface react
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				X
if facility is process	X			
Electrical				
Power supply	X			↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				↓
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT:
200450-001

TASK
03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

CP-36
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-36
External View

PREPARED FOR:



FREEPORT-McMoRAN

CP-37

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 03/14/2024

Facility: Wash
Pole & Pit

Facility tag: CP-37

PMLU Status:

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation		X		
Floor Slabs		X		
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				na
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				na
Water Supply if present	X			
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			na
if facility is process				
Electrical				
Power supply				na
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				na
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-37
External View

PREPARED FOR:  FREEPORT-McMoRAN

CP-38

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

IW+WN

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061


Date/Time: 2/5/24 14:33

Facility: P.V. Pump house Facility tag: CP 38

PMLU Status: Keep



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			<p>pooling & rusting of sheeting</p> <p>Water Tank + containment all good</p> <p>Add containment as separate feat.</p>
Drainage Around Facility			X	
Access to Facility	X			
Building Parking	N/A			
Fencing or Security	N/A			
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds	X			
Structure				
Framing: Walls	MD		X	<p>Sheeting @ foundation contact is rusted away</p>
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure	N/A			
Mechanical				
HVAC if present	N/A			
Water Supply if present	X			
Waste water if present	N/A		N/A	
Other utilities if present	X		N/A	
Fire protection if present				
Piping				
if facility is not building				
if facility is process	X			
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring				<p>N/A</p> <p>↓</p>
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External View

PREPARED FOR: F-M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External View

PREPARED FOR:  FREEPORT-McMoRAN




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External Damage

PREPARED FOR:  FREEPORT-McMoRAN





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External Damage

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
External Damage

PREPARED FOR:  FREEPORT- McMoRAN
--



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
Internal View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
Internal Damage

PREPARED FOR: F-M FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-38
Internal Damage

PREPARED FOR:  FREEPORT-McMORAN

CP-39

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2/6/24 0940

Facility: Hoist Hs

Facility tag: CD-39

PMLU Status: Remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			Converted to storage
Drainage Around Facility	X			
Access to Facility	X			
Building Parking			X	
Fencing or Security			X	
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			- Some minor exterior elem damage
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				↓
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				↓
if facility is process				
Electrical				
Power supply				↓
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				X
Wall systems				
roofing				
ceilings				
doors			X	
windows			X	
points of egress	X			



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External View

PREPARED FOR:  FREEPORT- McMoRAN
--




PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External Damage

PREPARED FOR:

FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
Internal View

PREPARED FOR:



FREEPORT-McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
Internal View

PREPARED FOR: F-M FREEPORT- McMORAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External View

PREPARED FOR: F&M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External View

PREPARED FOR:  FREEPORT-McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External View

PREPARED FOR:





PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-39
External View

PREPARED FOR:  FREEPORT-McMoRAN

CP-40

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061



Date/Time: 02/06/2024

9:50 am

Facility: Frother

Facility tag: 20-40

Tanks & pumps

PMLU Status: repairs

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs		X		cracking floor slabs
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building	X			
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-40
External View

PREPARED FOR:  FREEPORT-McMoRAN

CP-41

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/06/2024 9:20 AM

Facility: N9 HS

Facility tag: LP-411

Storage area

PMLU Status: remains



Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			water pooling around Base N9
Drainage Around Facility		X		
Access to Facility	X			
Building Parking				
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs				
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls	X			
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-41
External View

PREPARED FOR:



CP-44

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

Date/Time: 02/06/2024 9:00

Facility: Electrical Facility tag: CA-214

at course of Conveyor Drive PMLU Status: remaining




Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip frnds				
Structure				
Framing: Walls		X		Holes in wall
Framing: Roofs	X			
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress		X		1 Door



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-44
External View

PREPARED FOR: F&M FREEPORT- McMoRAN



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-44
External Damage

PREPARED FOR:  FREEPORT-McMORAN

CP-45

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 02/05/2021

2:30

Facility: ~~Tramway~~

Facility tag: CA-4345



Moly thickener

PMLU Status: Remains

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility				
Building Parking				
Fencing or Security				
Foundation				
Foundation		X		Cracked floor
Floor Slabs		X		
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls		X		Dents in surrounding walls
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				

under maintenance



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-45
External View

PREPARED FOR:  FREEPORT-McMORAN

CP-46

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061

Date/Time: 2/5/24 13:30

Facility: 45-46

Facility tag:

PMLU Status: *Keep*



IM + WM

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site				<i>Both security & 30 Security Bldgs "new"</i>
Drainage Around Facility				
Access to Facility				
Building Parking				
Fencing or Security				
Foundation				
Foundation				
Floor Slabs				
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

CP-46
External View

PREPARED FOR:  FREEPORT- McMORAN
--

Attachment D
Miscellaneous Area Field Forms and Photographs

Tailings

PROJECT: 200450-001	TASK 03
PREPARED BY: 	

PREPARED FOR: 
--



Date/Time: 02/05/2024 12:00

Facility: Tailings

Facility tag: T-01

office + shop PMLU Status: remaining

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security	X			
Foundation				
Foundation		X		crack
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls				
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present	X			
Water Supply if present	X			
Waste water if present	X			
Other utilities if present				
Fire protection if present				na
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring		X		crack floor
Wall systems	X			
roofing	X			
ceilings	X			
doors	X			
windows	X			
points of egress	X			



PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

Tailings External View

PREPARED FOR:





PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

Tailings External Damage

PREPARED FOR:



RES08

PROJECT: 200450-001	TASK 03
PREPARED BY: TELESTO SOLUTIONS INCORPORATED	

PREPARED FOR:  FREEPORT- McMoRAN
--

Res 8-01

PMLU BUILDING INSPECTION FORM				
Freeport-McMoran Chino Mine		Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061		
Date/Time: 07/11/2024 8:00 am	Facility: Storage	Facility tag: 96-2008/06/01	PMLU Status:	
Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs	X			
Framing: Internal	X			
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply	X			
Power distribution	X			
Lighting	X			
Other utilities if present				
Architectural				
Condition of Flooring	X			
Wall systems				
roofing				
ceilings				
doors	X			
windows				
points of egress				

Res 8-02

PMLU BUILDING INSPECTION FORM

Freeport-McMoran Chino Mine

Telesto Solutions Inc. 1303 N Pope St A, Silver City, NM 88061




Date/Time: 02/05/2024

8:15

Facility: Pump House Facility tag: CFS-2023/08/26

PMLU Status:

Category	Condition			Comments
	Good	Fair	Poor	
Civil				
Condition of Site	X			
Drainage Around Facility	X			
Access to Facility	X			
Building Parking	X			
Fencing or Security				
Foundation				
Foundation	X			
Floor Slabs	X			
If process Facility: Cond of equip fnds				
Structure				
Framing: Walls	X			
Framing: Roofs				
Framing: Internal				
If Concrete structure				
Mechanical				
HVAC if present				
Water Supply if present				
Waste water if present				
Other utilities if present				
Fire protection if present				
Piping				
if facility is not building				
if facility is process				
Electrical				
Power supply				
Power distribution				
Lighting				
Other utilities if present				
Architectural				
Condition of Flooring				
Wall systems				
roofing				
ceilings				
doors				
windows				
points of egress				



PROJECT:	TASK
200450-001	03
PREPARED BY:	
TELESTO SOLUTIONS INCORPORATED	

RES08
External View

PREPARED FOR:
 FREEPORT-McMoRAN



PROJECT:	TASK
200450-001	03

PREPARED BY:
TELESTO
SOLUTIONS INCORPORATED

RES08
External Damage & Internal View

PREPARED FOR:

